

5700 BALLISTICS WEATHER METER WITH HORNADY 4DOF - 5700 BALLISTICS WEATHER METER W/HORNADY 4DOF LINK SAND

Features At A Glance Has Hornady 4DoF Ballistics Solver built in to this meter Choose from a long range of match and hunting style bullets from Hornady Accounts for all variables that affect bullet trajectory Easy mode to get started quickly Rugged (drop tested to MIL-STD-810G standards), waterproof (sealed to IP67 standards). Protective pouch, neck lanyard and Lithium AA battery included. 5-year warranty. Long Range Accuracy is within your reach with the Kestrel 5700 Ballistics Weather Meter with 4DOF®. The Kestrel 5700 is a tremendous value in full-featured ballistics calculators. This integrated weather meter and ballistics solver takes the guesswork out of long-range shooting and is an ideal companion for hunters, competitive, and recreational shooters working to stretch their reach in long-range shooting. The Kestrel with Hornady 4DOF is a comprehensive, weather-proof ballistics meter built for unprecedented accuracy and uncompromising performance even in harsh environments. Whether you're up in the mountains on the hunt or down in the mud competing in a match, count on the Kestrel to keep working alongside you despite any challenging outdoor conditions. Leave your phone behind, and forget about apps - this unit is fully functional as a complete, durable field tool for achieving first-round hits. Combining complete onsite environmental measurements with Hornady 4DOF® trajectory solutions - this rugged all-in-one handheld unit delivers the convenience you want and the accuracy you need for long-range success under any conditions. The Kestrel 5700 is a tremendous value in full-featured ballistics calculators. This integrated weather meter and ballistics solver takes the guesswork out of long-range shooting and is an ideal companion for hunters, competitive, and recreational shooters working to stretch their reach in long-range shooting. Hornady 4DOF Ballistics Calculator The Hornady 4DOF Ballistics Calculator has been trusted by hundreds of thousands of long-range hunters and shooters since 2016. Ideal for precise long-range calculations using low-drag precision bullets, the Hornady 4DOF Ballistic Calculator provides trajectory solutions based on projectile Drag Coefficient (not ballistic coefficient) along with the exact physical modeling of the projectile and its mass and aerodynamic properties. Additionally, it calculates the vertical shift a bullet experiences as it encounters a crosswind; referred to as aerodynamic jump. The Hornady 4DOF also accurately calculates angled shots by accounting for important conditions. The Kestrel 5000 Series platform offers a large, high-resolution and contrast display with ease of font readability. It also includes a built-in dual color backlight, extra-strong polycarbonate lens, AA battery operation and LiNK iOS and Android wireless connectivity and app support. Like all Kestrel meters, the Kestrel 5700 is drop-tested, dust-proof, waterproof and able to withstand harsh environments without damage- so it can accompany you to the range or hunt for years to come. A range of carry pouch options makes it even easier to take your Kestrel 5700 with you. Buy the Kestrel 5700 with LiNK and get the power of the Kestrel LiNK Ballistics app for Android or the Kestrel Link Ballistics app for iOS for free. Build and manage your gun/bullet profiles and download them to your Kestrel 5700 before you set out. At the range or match, secure your Kestrel 5700 to a tripod using the optional Kestrel Vane Mount and use the app to quickly adjust the target range and view the shooting solution and wind rose without leaving your shooting position. It's like having a meteorologist and ballisticians standing next to you while you shoot. In addition to the ballistics solver capabilities, the Kestrel 5700 is a comprehensive weather meter for measurement and logging of primary



environmental conditions: wind speed and direction, temperature, humidity, heat index, pressure and altitude. Paired with the Vane Mount, the Kestrel 5700 Ballistics Weather Meter becomes a compact, easily-deployable weather station. Your data log can be transferred to a iOS/Android device wirelessly with the LiNK wireless communication option and Kestrel LiNK app, or to a Windows/Mac device with either the accessory Kestrel LiNK Dongle or waterproof USB Data Transfer Cable (Both sold separately). Kestrels have been put to the test in some of the harshest conditions on the planet. U.S. Special Forces, combat weather teams, wildland firefighters, smoke jumpers, Mt. Everest expeditions and auto pit crews are just a few who rely on a Kestrel to provide them with the crucial environmental data they need. Watch any on-screen meteorologist during a hurricane, and you're sure to spot a Kestrel in action. With a Kestrel 5700, you can put accurate shooting solutions and environmental measurements in the palm of your hand, anywhere your adventure takes you.

Attributes

- Name: 5700 BALLISTICS WEATHER METER W/HORNADY 4DOF LINK SAND
- Manufacturer: KESTREL
- Product no.: 430103604
- Mfr. No.: 0857HLSND
- Color: Sand
- Delivery weight: 0.34kg
- Shipping height: 38mm
- Shipping width: 165mm
- Shipping length: 165mm

Item details

Made in USA

Table of Contents

- [Startpage](#)
- [English: Safety Instruction Guide for the Kestrel 5700 Ballistics Weather Meter with Hornady 4DOF](#)
- [Svenska: Säkerhetsinstruktioner för Kestrel 5700 Ballistics Weather Meter med Hornady 4DOF](#)

Safety Instruction Guide for the Kestrel 5700 Ballistics Weather Meter with Hornady 4DOF

Introduction

Thank you for choosing the Kestrel 5700 Ballistics Weather Meter with Hornady 4DOF. This guide provides essential safety instructions to ensure the safe and effective use of your device. Please read this guide carefully before using the product.

General Safety Guidelines

- Ensure the product is used in accordance with the instructions provided in this guide.
- Keep the device out of reach of children and vulnerable individuals to prevent misuse or accidents.
- Regularly check for any signs of damage or wear on the device. If damaged, discontinue use immediately.
- Avoid exposing the device to extreme temperatures, moisture, or direct sunlight for prolonged periods.
- Do not attempt to disassemble or modify the device, as this may compromise its safety and functionality.
- Always use the device in a safe environment, free from distractions that may affect your focus while shooting.

Specific Safety Precautions for Use

- When using the Kestrel 5700, ensure that you are in a safe shooting position and that the area is clear of bystanders.
- Do not rely solely on the device for shooting decisions; always apply your judgment and experience.
- Ensure that the battery compartment is securely closed to prevent moisture from entering the device.
- Use only the recommended Lithium AA batteries. Improper battery use may lead to leakage or device malfunction.
- Be aware of your surroundings and local regulations regarding the use of firearms and shooting practices.
- If you experience any malfunction or irregular behavior from the device, cease use immediately and consult a professional.

Instructions for Installation and Usage

1. Battery Installation

- Open the battery compartment by sliding the cover off.
- Insert the Lithium AA batteries, ensuring the correct polarity (+/-) is observed.
- Replace the battery compartment cover securely.

2. Powering On the Device

- Press and hold the power button until the display activates.
- Allow the device to initialize before taking measurements.

3. Using the Ballistics Calculator

- Select the appropriate bullet profile from the Hornady 4DOF database.
- Input environmental variables such as temperature, humidity, and wind speed.
- Follow onscreen prompts to calculate trajectory solutions.

4. Measuring Environmental Conditions

- Position the device away from obstructions to obtain accurate wind and temperature readings.

- Use the Vane Mount to stabilize the device for consistent measurements.

5. Data Transfer

- Connect your Kestrel 5700 to a compatible device using the Kestrel LiNK app for data management.
- Follow the app instructions for transferring data wirelessly.

6. Cleaning and Maintenance

- Clean the exterior using a soft, damp cloth. Avoid using harsh chemicals.
- Store the device in a protective pouch when not in use to prevent damage.

Disposal Instructions

- Dispose of the Kestrel 5700 and its accessories in accordance with local regulations.
- Do not dispose of Lithium AA batteries in household waste. Follow local guidelines for battery recycling or disposal.

Contact Information for Further Support

For any inquiries or further assistance regarding the Kestrel 5700 Ballistics Weather Meter, please refer to the manufacturer's website or customer support resources.

By following these safety guidelines and instructions, you can ensure a safe and effective experience with your Kestrel 5700 Ballistics Weather Meter with Hornady 4DOF. Thank you for choosing our product, and enjoy your shooting experience!

Säkerhetsinstruktioner för Kestrel 5700 Ballistics Weather Meter med Hornady 4DOF

Introduktion

Tack för att du valt Kestrel 5700 Ballistics Weather Meter med Hornady 4DOF. Denna enhet är designad för att ge exakta mätningar av väderförhållanden och ballistiklösningar för långdistansskytte. För att säkerställa säker användning och optimal prestanda, vänligen läs igenom dessa säkerhetsinstruktioner noggrant.

Allmänna säkerhetsriktlinjer

- Använd produkten endast för det avsedda syftet som beskrivs i användarmanualen.
- Förvara enheten på en säker plats borta från barn och andra sårbara grupper.
- Kontrollera enheten regelbundet för skador eller slitage. Använd inte enheten om den är skadad.
- Följ alltid lokala lagar och bestämmelser gällande användning av mätinstrument och skytteutrustning.

Specifika säkerhetsåtgärder för användning

- Använd enheten i enlighet med tillverkarens instruktioner för att undvika risker.
- Var medveten om omgivande väderförhållanden, inklusive vind och nederbörd, som kan påverka mätningar.
- Använd alltid skyddsutrustning, som hörselskydd och skyddsglasögon, när du använder skjutvapen.
- Lämna inte enheten obevakad i extrema väderförhållanden, såsom kraftig regn eller snö.
- Undvik att använda enheten i områden med stark elektromagnetisk störning.

Instruktioner för installation och användning

1. Installation

- Ta bort enheten från förpackningen och inspektera den för eventuella skador.
- Sätt i Lithium AAbatteriet enligt anvisningarna i manualen.
- Om enheten har ett skyddande fodral, se till att det är korrekt installerat för att skydda mot stötar och väder.

2. Användning

- Slå på enheten genom att trycka på strömbrytaren.
- Välj önskad funktion (t.ex. vädermätning eller ballistiklösning) genom att använda navigeringsknapparna.
- Följ anvisningarna på skärmen för att mata in nödvändiga data, som projektiltyp och avstånd.
- Använd Kestrel LiNKappen för att hantera vapen och kulprofiler och för att överföra data till din smartphone.

Avfallshantering

- Kasta inte enheten i hushållsavfall. Följ lokala bestämmelser för avfallshantering.
- Återvinn förpackningsmaterial och batterier enligt lokala riktlinjer.
- Om enheten är trasig eller inte längre behövs, kontakta en återvinningscentral för korrekt hantering.

Kontaktinformation för vidare support

För frågor eller mer information om produkten, vänligen kontakta tillverkaren eller din återförsäljare. Se till att

ha produktens modellnummer och inköpsinformation tillgänglig för snabbare service.

Viktig information

Kestrel 5700 Ballistics Weather Meter är testad för att klara tuffa miljöer och är vattentålig enligt IP67standarder. Den är också falltestad enligt MILSTD810Gstandarder. Trots detta rekommenderas det att alltid hantera enheten varsamt och följa säkerhetsriktlinjerna ovan för att säkerställa långvarig och säker användning.

Genom att följa dessa riktlinjer kan du maximera säkerheten och effektiviteten hos din Kestrel 5700 Ballistics Weather Meter med Hornady 4DOF. Tack för att du tar dig tid att läsa dessa instruktioner.