

MEC LEAD CHARGE BAR PROGRESSIVE PRESS - 1OZ LEAD SHOT CHARGE BAR

[Reloading](#) > [Reloading Presses](#) > [Reloading Press Accessories](#)

The MEC Charge Bars allow you to adjust your shot charge and enable you to create the load you desire. Interchanges with the charge bar which is included with your reloading press. Available in both lead and steel styles for single stage and progressive presses. Steel shot bars are available by special order.



Attributes

- Name: [1OZ LEAD SHOT CHARGE BAR](#)
- Manufacturer: [MEC RELOADING](#)
- Product no.: 749009381
- Mfr. No.: 100502100
- Size: 1 oz
- Delivery weight: 0.24kg
- Shipping height: 25mm
- Shipping width: 25mm
- Shipping length: 160mm
- UPC: 098489015394

Item details

Made in USA

Table of Contents

- Startpage
- MEC Lead Charge Bar Progressive Press 1oz Lead Shot Charge Bar Safety Instruction Guide
- About Us

MEC Lead Charge Bar Progressive Press 1oz Lead Shot Charge Bar Safety Instruction Guide

Introduction

Thank you for choosing the MEC Lead Charge Bar Progressive Press 1oz Lead Shot Charge Bar. This product is designed to help you customize your shot charge for reloading, ensuring you can create the loads you desire. It is important to follow safety guidelines to ensure safe and effective use of this product.

General Safety Guidelines

- Ensure that you read and understand all instructions before using the MEC Lead Charge Bar.
- Always wear appropriate personal protective equipment (PPE), including safety glasses and gloves, when handling lead shot or reloading components.
- Keep the work area clean and free of clutter to prevent accidents.
- Store the charge bar and all reloading components in a cool, dry place, away from children and pets.
- Regularly inspect the charge bar for any signs of wear or damage before use.
- Follow all local laws and regulations regarding the use and storage of reloading equipment and materials.

Specific Safety Precautions for Use

- Avoid using the charge bar if it is damaged or malfunctioning.
- Do not exceed the recommended charge weight as specified in your reloading data.
- Use only compatible components with the MEC Lead Charge Bar to avoid malfunctions.
- Ensure that the reloading press is securely mounted and stable before use.
- Be cautious of lead exposure; wash hands thoroughly after handling lead shot and avoid eating or drinking in the work area.
- If you experience any discomfort or adverse reactions while using this product, discontinue use immediately and seek medical advice.

Instructions for Installation and Usage

Installation

1. **Preparation:** Ensure that your reloading press is turned off and unplugged before beginning installation.
2. **Remove Existing Charge Bar:** If applicable, carefully remove the existing charge bar from your reloading press.
3. **Install MEC Lead Charge Bar:**
 - Align the MEC Lead Charge Bar with the mounting points on your reloading press.
 - Securely fasten the charge bar in place according to the manufacturer's instructions.
4. **Check Alignment:** Ensure that the charge bar is properly aligned and functioning smoothly before proceeding.

Usage

- **Adjusting Shot Charge:**
 - Use the adjustment mechanism on the charge bar to set the desired shot weight.
 - Refer to your reloading data for appropriate charge weights.
- **Loading:**
 - Load the charge bar with lead shot according to the manufacturer's instructions.
 - Ensure that the shot is evenly distributed within the charge bar.
- **Final Check:** Before beginning the reloading process, doublecheck that all components are secure and functioning correctly.

Disposal Instructions

- Dispose of any unused lead shot and reloading materials in accordance with local regulations.
- Do not dispose of lead shot in regular household waste. Check with local authorities for proper disposal methods.
- Clean the work area thoroughly after use to prevent lead contamination.

Contact Information for Further Support

For any safety inquiries or further assistance regarding the MEC Lead Charge Bar, please refer to the manufacturer's contact information provided with the product packaging or visit the official MEC website.

By following these safety instructions, you can ensure a safe and effective reloading experience with the MEC Lead Charge Bar Progressive Press 1oz Lead Shot Charge Bar. Always prioritize safety and adhere to local regulations regarding reloading practices. Thank you for your commitment to safety!

About Us

Brownells Austria

Brownells - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

www.brownells.at