

NO-GO HEADSPACE GAUGES - NO GO 30-30 WINCHESTER HEADSPACE GAUGE STEEL

[Gunsmith Tools & Supplies](#) > [Measuring Tools](#) > [Headspace Gauges](#)

Absolutely Essential For Accurate, Safe, Chamber Work

CLYMER NO-GO HEADSPACE GAUGES The Clymer No-Go Headspace Gauges are precision tools designed to help gunsmiths and firearm enthusiasts verify that a firearm's chamber does not exceed the maximum safe headspace dimensions. By identifying excessive chamber length, these gauges prevent potential safety hazards such as case ruptures or misfires, ensuring the firearm operates within the specified tolerances. They are essential during the chambering of new barrels, routine maintenance, or when assessing used firearms for purchase. Key Features: Precision Machining: Each gauge is crafted from high-quality steel and machined to exact SAAMI specifications, ensuring accurate and reliable measurements. Caliber Specificity: Available in a wide range of calibers, these gauges cater to various firearm types, providing versatility for gunsmiths working with multiple platforms. Durable Construction: Built to withstand repeated use, the hardened steel construction ensures longevity and consistent performance in demanding workshop environments. Specifications: Material: Hardened steel Dimensions: Size varies with caliber and gauge style Compliance: Manufactured to SAAMI specifications Customer Insights: Customers value the Clymer No-Go Headspace Gauges for their precision and reliability. The accurate machining and adherence to industry standards provide confidence during firearm assembly and inspection processes. Users appreciate the wide range of available calibers, allowing them to select the appropriate gauge for their specific needs. The durable construction is frequently highlighted, with many noting that the gauges maintain their accuracy even after extensive use. Incorporating the Clymer No-Go Headspace Gauges into your gunsmithing toolkit ensures that your firearm chambers are within safe operational limits, enhancing both safety and performance.



Attributes

- Name: [NO GO 30-30 WINCHESTER HEADSPACE GAUGE STEEL](#)
- Manufacturer: [CLYMER](#)
- Product no.: 184100301
- Mfr. No.: NG30/30WCF
- Cartridge: 30-30 Winchester,357 Herrett,219 Donaldson Wasp,219 Zipper,32 Winchester Special,25-35 Winchester,7-30 Waters,30 Herrett,303 Savage,307 Winchester,32-40 Winchester,356 Winchester,375 Winchester
- Color: Steel
- Height: 0.4"
- Length: 0.73"
- Material: Steel
- Model Number: 30-30 Winchester NO GO
- Style: No Go Gauge
- Weight: 0.1 lbs
- Width: 0.4"
- Delivery weight: 0.023kg
- Shipping height: 25mm

- Shipping width: 66mm
- Shipping length: 64mm

Item details

Made in USA

Table of Contents

- [Startpage](#)
- [Clymer NoGo Headspace Gauges Safety Instructions](#)
- [About Us](#)

Clymer NoGo Headspace Gauges Safety Instructions

Introduction

Thank you for choosing the Clymer NoGo Headspace Gauges. These precision tools are designed to ensure the safe operation of firearms by verifying that the chamber does not exceed maximum safe headspace dimensions. This guide provides essential safety instructions to help you use these gauges effectively and responsibly.

General Safety Guidelines

- Always handle firearms and related tools with care and respect.
- Ensure that the gauge is compatible with your specific firearm caliber.
- Keep the gauges out of reach of children and vulnerable individuals.
- Regularly inspect the gauges for any signs of damage or wear.
- Use the gauges in a welllit and organized workspace to prevent accidents.
- Follow all local laws and regulations regarding firearms and their accessories.

Specific Safety Precautions for Use

- Before using the gauge, ensure that the firearm is unloaded and pointed in a safe direction.
- Do not force the gauge into the chamber; if it does not fit, recheck compatibility.
- Always wear safety glasses when using firearms and related tools.
- Avoid using the gauge if it shows signs of damage or if it has been modified.
- Store the gauges in a protective case to prevent damage and maintain accuracy.

Instructions for Installation and Usage

1. Preparation:

- Ensure the firearm is unloaded.
- Gather your Clymer NoGo Headspace Gauge and any necessary tools.

2. Using the Gauge:

- Insert the NoGo Gauge into the chamber of the firearm.
- Gently close the bolt or action of the firearm.
- If the bolt does not close completely, the headspace is within safe limits. If the bolt closes fully, the chamber exceeds safe headspace dimensions.

3. PostUse Care:

- Remove the gauge from the chamber after use.
- Clean the gauge with a soft cloth to remove any debris or residue.
- Store the gauge in its designated case or location.

Disposal Instructions

- Dispose of any damaged or worn gauges in accordance with local regulations.
- Do not throw gauges in regular trash; check for recycling options or hazardous waste disposal guidelines.

Contact Information for Further Support

For any questions or concerns regarding the use of the Clymer NoGo Headspace Gauges, please refer to the manufacturer's website or contact your local dealer for assistance.

By following these safety instructions, you can ensure the proper and safe use of your Clymer NoGo Headspace Gauges. Thank you for prioritizing safety in your firearms handling and maintenance.

About Us

Brownells Austria

Brownells - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

www.brownells.at