

WAA410HS 410 BORE SHOTSHELL WADS - CLAYBUSTER 410 GAUGE 1/2OZ WADS FOR WAA410HS RED 500/BAG

[Reloading](#) > [Wads](#)

CB5050-410HS is for use in 1/2 oz. Winchester, Remington, or Federal hulls.
Optimum load is 1/2 oz.



Attributes

- Name: [CLAYBUSTER 410 GAUGE 1/2OZ WADS FOR WAA410HS RED 500/BAG](#)
- Manufacturer: [CLAYBUSTER](#)
- Product no.: 940002571
- Mfr. No.: CB5050-410HS
- Gauge: .410 Gauge
- Quantity: 500
- Delivery weight: 0.34kg
- Shipping height: 152mm
- Shipping width: 178mm
- Shipping length: 254mm
- UPC: 743491050504

Item details

Made in USA

Table of Contents

- Startpage
- Safety Instruction Guide for WAA410HS 410 Bore Shotshell Wads
- About Us

Safety Instruction Guide for WAA410HS 410 Bore Shotshell Wads

Introduction

Thank you for choosing the WAA410HS 410 Bore Shotshell Wads by Claybuster. This guide provides important safety information to ensure the safe use of this product. Please read this guide thoroughly before using the wads.

General Safety Guidelines

- Ensure that the product is used only for its intended purpose.
- Store wads in a cool, dry place away from direct sunlight and moisture.
- Keep out of reach of children and vulnerable individuals.
- Always wear appropriate safety gear, including eye protection, when handling ammunition.
- Be aware of your surroundings and ensure you are in a safe location when loading and firing.

Specific Safety Precautions for Use

- Only use the WAA410HS wads with 1/2 oz. Winchester, Remington, or Federal hulls.
- Do not exceed the recommended load specifications to avoid excessive pressure.
- Inspect all components of the shotshell before use. Discard any that are damaged or show signs of wear.
- Follow all local laws and regulations regarding the use of ammunition and shooting sports.
- If you experience any malfunctions or misfires, follow proper safety protocols for handling such situations.

Instructions for Installation and Usage

1. Preparation:

- Gather all necessary components: WAA410HS wads, hulls, powder, and shot.
- Ensure that your workspace is clean and organized.

2. Loading the Shotshell:

- Open the hull and place the WAA410HS wad in the base of the hull.
- Add the appropriate amount of powder as per the load data.
- Carefully add the shot to the hull, ensuring it is level with the top of the wad.
- Crimp the hull securely to prevent any leakage of the shot.

3. Firing:

- Always check your firearm to ensure it is in good working condition.
- Load the shotshell into the firearm according to the manufacturer's instructions.
- Aim in a safe direction and be aware of your target and what lies beyond it.
- Fire the shotshell only when you are certain it is safe to do so.

4. PostUse:

- After use, clean your firearm according to the manufacturer's recommendations.
- Dispose of any spent hulls and wads responsibly.

Disposal Instructions

- Dispose of used wads and hulls in accordance with local regulations.
- Do not litter; use designated waste disposal methods.
- If you have any unused or expired products, contact local waste management for proper disposal options.

Contact Information for Further Support

For safety inquiries or more information about the WAA410HS 410 Bore Shotshell Wads, please reach out to the designated EU contact point or refer to the packaging for further assistance.

Conclusion

By following these safety instructions, you can help ensure a safe and enjoyable experience with your WAA410HS 410 Bore Shotshell Wads. Always prioritize safety and adhere to local regulations regarding ammunition and shooting practices. Thank you for choosing Claybuster products.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk