

Spuhr Adapter for Sidemounted Bubble Level

[Gunsmith Tools](#) > [Measuring Tools](#) > [Levels](#)

With this adapter you can easily attach your sidemounted bubble level from Ulfhednar onto your Spuhr sight mount.

NO IMAGE
AVAILABLE

Attributes

- Name: [ULFHEDNAR Spuhr Adapter for Sidemounted Bubble Level](#)
- Manufacturer: [ULFHEDNAR](#)
- Product no.: EU2002534
- Mfr. No.: UH356
- Delivery weight: 0.01kg
- EAN: 0745114707826

Table of Contents

- [Startpage](#)
- [ULFHEDNAR Spuhr Adapter for Sidemounted Bubble Level Safety Instructions](#)
- [About Us](#)

ULFHEDNAR Spuhr Adapter for Sidemounted Bubble Level Safety Instructions

Introduction

Thank you for choosing the ULFHEDNAR Spuhr Adapter for your sidemounted bubble level. This guide provides essential safety instructions to ensure safe and effective use of the product. Please read and follow these guidelines carefully to avoid any hazards.

General Safety Guidelines

- Always ensure that the adapter is compatible with your specific Spuhr sight mount before installation.
- Inspect the adapter and the bubble level for any visible damage before use. Do not use if damaged.
- Keep the product out of reach of children to prevent accidents or misuse.
- Use the adapter only for its intended purpose as described in this manual.
- If you experience any issues or concerns during use, discontinue use immediately and seek assistance.

Specific Safety Precautions for Use

- Ensure that the bubble level is securely attached to the adapter before use.
- Avoid using the adapter in extreme weather conditions that may affect its performance.
- Do not apply excessive force when attaching or detaching the bubble level to prevent damage.
- Regularly check the adapter and bubble level for wear and tear, and replace if necessary.
- Be cautious of sharp edges or components that may cause injury during installation or use.

Instructions for Installation and Usage

1. Installation

- Ensure your Spuhr sight mount is clean and free from debris.
- Align the ULFHEDNAR adapter with the designated attachment point on the sight mount.
- Gently press the adapter into place until it clicks securely. Ensure it is firmly attached.
- Attach the sidemounted bubble level to the adapter by aligning it with the attachment mechanism.
- Secure the bubble level by following the manufacturer's instructions for your specific model.

2. Usage

- Once installed, check that the bubble level is functioning correctly and is calibrated.
- Use the bubble level to ensure accurate measurements as needed.
- After use, detach the bubble level from the adapter if not needed for extended periods.
- Store the adapter and bubble level in a safe, dry place to prevent damage.

Disposal Instructions

- Dispose of the ULFHEDNAR Spuhr Adapter and any associated components in accordance with local regulations.
- Do not dispose of the product in general household waste. Check for recycling options or designated collection points for electronic waste.

Contact Information for Further Support

For any questions, concerns, or to report unsafe products, please refer to your local authorities or the

appropriate consumer safety organization in your area.

Thank you for your attention to these safety instructions. Your safety and satisfaction are our top priorities.
Enjoy using your ULFHEDNAR Spuhr Adapter!

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk