

ACI-Angle Cosine Indicator - SWK-Holder with Bubble Level D30u.D34

High-Angle Trajectory Correction: Precision shooting at extreme long ranges or steep uphill/downhill angles demands precise trajectory adjustments to compensate for gravity's altered effect on bullet flight. The integrated Angle Cosine Indicator (ACI) provides immediate data required to calculate exact holdovers or turret corrections.



Eliminate Rifle Cant: The highly visible bubble level assists the shooter in maintaining a perfectly level platform, eliminating horizontal impact drifts caused by subtle weapon canting.

Seamless UNIVERSAL Integration: Designed to mount directly to the ERATAC UNIVERSAL interface, this compact unit retrofits onto your existing setup without requiring you to shift or reinstall your riflescope. Its minimalist footprint makes it fully compatible with ultra-short main tube optics, such as the Schmidt and Bender PMII.

Optimized Ergonomic Placement: The ACI is strategically positioned at the optical centerline to virtually eliminate parallax viewing errors, ensuring the entire scale remains readable while behind the rifle. The layout is engineered to clear left-side illumination dials, allowing operators to check data instantly while in the shooting position.

Duty-Grade Submersible Reliability: Manufactured to rigorous Mil-Spec standards, the unit is fully waterproof and submersible up to a depth of 1 meter for 35 minutes.

Unobstructed Turret Visibility: The integrated bubble level features a precise lateral offset, guaranteeing an entirely clear, line-of-sight view to your main elevation turret adjustments.

Attributes

- Name: SWK-Holder with Bubble Level D30u.D34
- Manufacturer: ERATAC
- Product no.: EU2018067
- Mfr. No.: T0940-0000
- Colour: Black
- Delivery weight: 1kg
- Shipping height: 100mm
- Shipping width: 100mm
- Shipping length: 100mm
- EAN/UPC: T0940-0000

Table of Contents

- [Startpage](#)
- [English: ACIAngle Cosine Indicator SWKHolder with Bubble Level D30u.D34 Safety Instruction Guide](#)

ACIAngle Cosine Indicator SWKHolder with Bubble Level D30u.D34 Safety Instruction Guide

Introduction

Thank you for choosing the ACIAngle Cosine Indicator SWKHolder with Bubble Level D30u.D34. This product is designed to enhance your shooting accuracy by providing precise angle adjustments and ensuring a level shooting platform. To ensure safe and effective use, please read this safety instruction guide carefully.

General Safety Guidelines

- **Product Safety:** This product has been designed and manufactured to meet strict safety standards. Always use it according to the instructions provided.
- **Enhanced Recalls:** In the unlikely event of a product recall, you will be notified through standardized recall notices. Please ensure you register your product to receive such notifications.
- **Online Shopping:** Whether purchased online or instore, this product meets the same safety standards. Ensure you buy from authorized retailers.
- **Special Consumer Focus:** Extra care should be taken when this product is used by or around vulnerable groups, such as children.
- **EU Contact Point:** For any safety inquiries, please refer to the designated EU contact point.
- **Rapid Alerts:** Stay informed about any safety updates or alerts regarding this product through the EU's Safety Gate platform.

Specific Safety Precautions for Use

- **Rifle Stability:** Always ensure your rifle is stable before making adjustments with the ACI. Unstable positioning can lead to accidents.
- **Leveling:** Use the integrated bubble level to confirm that your rifle is level before taking any shots. This helps to avoid horizontal impact drifts.
- **Angle Adjustments:** Make sure to correctly interpret the readings from the Angle Cosine Indicator to adjust for steep angles and longrange shooting.
- **Environmental Awareness:** Be aware of your surroundings and ensure your shooting area is safe and free from obstructions.
- **Maintenance:** Regularly check the ACI for any signs of damage or wear. Do not use if damaged.
- **Age Restrictions:** This product is not intended for use by children. Ensure that it is used only by individuals who are trained and experienced in shooting.

Instructions for Installation and Usage

1. Installation:

- Ensure the rifle is unloaded and pointed in a safe direction.
- Locate the ERATAC UNIVERSAL interface on your rifle.
- Mount the ACIAngle Cosine Indicator directly onto the interface, ensuring a secure fit.
- Verify that the unit is properly aligned with your riflescope.

2. Usage:

- Before shooting, confirm that the bubble level indicates a level position.
- Use the Angle Cosine Indicator to assess the shooting angle. Adjust your aim accordingly based on the readings.
- Regularly check the bubble level throughout your shooting session to maintain a level platform.
- After use, detach the ACI if necessary and store it in a safe, dry place.

Disposal Instructions

- When disposing of the ACIAngle Cosine Indicator, please follow local regulations for electronic waste disposal.
- Do not dispose of the product in regular household waste.
- Consider recycling options available in your area to minimize environmental impact.

Contact Information for Further Support

For any questions or concerns regarding the ACIAngle Cosine Indicator SWKHolder with Bubble Level D30u.D34, please refer to the designated EU contact point. Ensure you have your product details ready for assistance.

Thank you for your attention to these safety instructions. Enjoy your shooting experience with the ACIAngle Cosine Indicator!